


Map of Stencil Fabrication



1. Stencil Laser
2. Controller
3. PC with BoardMaster
4. Bench to prepare the stencil
5. Sheet metal stock
6. Framing table
7. Glueing table
8. Frame stock
9. PC with CircuitCAM
10. Coloring of fiducial marks
11. Ultrasonic
12. Cleaning desk
13. Packing table
14. Compressor
15. Exhauster
16. Cooling System

Technical contents of this document are subject to change without notice.